

# GX-3R Pro Quick Reference Guide

## Turn On

Press & Hold

**POWER  
MODE**

## Past Due Bump/CAL

To Bump / CAL

**POWER  
MODE**

Confirm & Use

**AIR**

♥✓	7:49	📶	🔊	🔋
CONFIRM TO USE USER MODE:MODE NO :AIR				
BUMP DATE PAST				
♥✓	7:49	📶	🔊	🔋
CONFIRM TO USE USER MODE:MODE NO :AIR				
CAL DATE PAST				

## Normal Operation

After brief  
warm-up period

♥✓	7:49	📶	🔊	🔋	
CH4	%LEL	CO	ppm	H2S	ppm
	0		0		0.0
O2	%	CO2	vol%		
	20.9		0.00		

## Fresh Air

Press & Hold


**AIR**

## Turn Off

Press & Hold

**POWER  
MODE**

# GX-3R Pro Quick Reference Guide



Scan QR code for  
GX-3R Pro Manual

RKI Instruments, Inc. 33248 Central Ave, Union City, CA 94587

Phone (510) 441-5656 • (800) 754-5165 • [www.rkiinstruments.com](http://www.rkiinstruments.com)

190422/250

